

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

10 JUN 1981

810605

NJS 000 001 033

## A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name American Cyanamid Company  
Street One Cyanamid Plaza  
City Wayne State NJ Zip Code 07470

## B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site AMERICAN CYANAMID CO., Linden Warehouse Site  
Street 3401 Tremley Point Road  
City Linden County Union State NJ Zip Code 07036

## C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Hathaway, Stuart, R., Mgr. Environmental Services  
Phone (201) 862-6000

## D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1947\* To (Year) 1980\*

\*Dates of disposal at referenced site

## E Waste Type: Choose the option you prefer to complete

**Option 1:** Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

### General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☒ Organics
2. ☒ Inorganics
3. ☒ Solvents
4. ☒ Pesticides
5. ☒ Heavy metals
6. ☒ Acids
7. ☒ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

### Source of Waste:

Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☒ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

**Option 2:** This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

### Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.




181903



**F Waste Quantity:**

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

**Facility Type**

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) \_\_\_\_\_

**Total Facility Waste Amount**

cubic feet ~~Unknown~~

gallons ~~Unknown~~

**Total Facility Area**

square feet -

acres 30 ~~1~~

Landfill Area Ca 9.3 Acres

9A

**G Known, Suspected or Likely Releases to the Environment:**

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☒ Suspected ☐ Likely ☐ None

**Note:** Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

**H Sketch Map of Site Location: (Optional)**

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

**I Description of Site: (Optional)**

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

(The site was used to landfill wastes generated at Cyanamid's Warners Plant. No outside wastes were landfilled at the site. Wastes were landfilled in a single lift and covered daily. The landfill was covered with clay, the clay compacted to achieve a permeability rate of  $1 \times 10^{-7}$  cm/sec. and the clay was covered with topsoil and seeded.

Closure was completed per the Engineering Closure Plan prepared by the N. J. Department of Environmental Protection. Closure was completed in September 1980. There are no nearby wells, springs, lakes or housing. Monitoring wells have been installed and they are sampled and analyzed quarterly. The site is reached through Cyanamid's gate off of South Wood Avenue. The site was most recently inspected by the NJDEP on March 26, 1981 and by EPA's contractor (F. Hart & Assoc.) on March 30, 1981.)

**J Signature and Title:**

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name American Cyanamid Company

Street Post Office Box 31

City Linden State NJ Zip Code 07036

Signature *J. B. Halladay* Date 6/5/81

G. B. Halladay Plant Manager

- ☒ Owner, Present  
☐ Owner, Past  
☐ Transporter  
☐ Operator, Present  
☒ Operator, Past  
☐ Other



**American Cyanamid Company**  
Post Office Box 31  
Linden, NJ 07036

**CERTIFIED**  
**No. 825700**  
**MAIL**

Sites Notification  
Region II  
U. S. Environmental Protection Agency  
New York, New York 10278

